

Please note that the BRM Civic Association only makes recommendations to the County. The County takes our recommendations into account, but is the final authority in terms of which projects get funding.

TASK ORDERS UNDER CONSIDERATION				
Priority	Damage	Location	Notes	Status
1	Potholes		Known potholes in expanded list below	Sent to County PM on 4/22/12 for cost estimate
		Duffy 1521		
		Gore 1907		
		Gore 2008	Major pothole damage	
		Gore 2200	North of location over culvert & along driveway	
		Gore 2303		
		Gore 2307	Both sides, north & south of address	
		Gore 2430		
		Hickory	Near end of road	
		Lookout 2315		
		Lookout 2508		
		Lookout 2602	South of driveway	
		Lookout & Sumney	At intersection and south up the hill	
		Mercer 1405		
		Mercer 1601		
		Mercer 1607		
		Mercer 1613		
		Mercer 1616	Just south of 1616 at edge of road	
		Quaker & Mountain	Potholes at intersection	
		Ridge & Gore	Inside curve of ridge	
		Ridge & Hickory		
		Summit 1619	50 yards north down the hill	
		Sumney 6100	South uphill side of road beyond 6100	
		Sumney 16300	Multiple on way up to 16300 from Wyle terrace	
		Warburton 15942		
		Warburton 15948	Multiple down to summit	
2	Ditch/Culvert Fix		Known trouble areas in expanded list below	Sent to County PM on 4/22/12 for cost estimate
		Gore 2008	West side all the way down to the culvert	
		Lookout 2602	Driveway has eroded over road	
		Nelson 15701	West side of driveway at 15701	
		Nelson 15710	Ditch erosion	
		Ridge & Gore	Southwest corner	
		Ridge & Hickory		
		Warburton 15918	Multiple, south side for 100 yards	
3	Poor Condition of Road	Upper Jackson	Needs to be tar & chipped	Sent to County PM on 4/22/12 for cost estimate
4	Poor Condition of Road	Lookout North	Needs to be tar & chipped	Sent to County PM on 4/22/12 for cost estimate
5	Poor Condition of Road	Jackson 2912	Large dip in roadway needs to be filled	Sent to County PM on 4/22/12 for cost estimate
6	Resurfacing of Tar& Chip	TBD	We need to determine if, when, and where we start this work	Sent to County PM on 4/22/12 for cost estimate
7	Poor Condition of Road	Ridge	Road widening for recent addition into our system	Sent to County PM on 4/22/12 for cost estimate
?	Turnarounds		Should be reviewed with Evergreen FD before we commit to work	Sent to County PM on 4/22/12 for cost estimate
		Upper Jackson	North of Sumney	
		Lookout North		
		Summit		
		Warburton		
		Mercer		
		Judy Terrace	If they could do something about access into Judy, and the corner of Tansill and Rodgers that would be an improvement. Judy itself is difficult and that turn is not accessible in a fire truck.	
		Duffey Dr (and Ct)		
		Lookout South	Lower fork needs repair, widened, turn around	
?		Lower & Middle Jackson	Should we connect these two roads?	Sent to County PM on 4/22/12 for cost estimate

Notes

Per VA Dept of Forestry, the \$7,500 Firewise Grant, which must be used by August 2012, can only be used for turn-arounds (can apply grant to all turn-around work except for tar & chip). Resurfacing is #6 on our priority list. However, the roadway will be divided in to smaller sections based upon need. As a result, certain sections may move higher on the priority list.

Notes for County PM

Potholes

Requesting estimate to fix all potholes. Please include scalloping/side holes where paved surface has eroded at the edge of the roadway.

Ditches/Culverts

Requesting estimate to first clear ditches of leaves (so we can assess condition) before recommending specific sections to be re-dug or have rock removed/enlarged.

Please break-out clearing/unplugging of culverts.

One ditch that needs a cleanout is lower Nelson (near Mountain Road), south side. It was deep but has filled with gravel all the way down to the new culvert VDOT put under Mountain Rd and now runoff spreads gravel onto Mountain Road.

Upper Jackson

Requesting estimate for grade 21a gravel, compact, then tar and chip (immediately before rain can wash away).

Lookout North

Requesting estimate for grade 21a gravel, compact, then tar and chip (immediately before rain can wash away).

Jackson 2912

Requesting estimate to excavate dip in roadway, investigate cause, fill and re-pave.

Resurfacing

Please request that the contractor identify/recommend/estimate cost for road segments most in need of resurfacing and prioritize (e.g., the stretch of Gore where Miller potholes have compromised an entire segment of roadway).

Ridge

Requesting estimate for the private drive on Ridge that got incorporated into our system to be widened by 4 feet on the southern side.

Turnarounds

Requesting estimate for pre-tar & chip and tar & chip activities. We must have these activities split in to separate estimates to take advantage of Firewise Grant.

The proposed turnarounds will need land-owners approvals for part of the work.

Lower-Middle Jackson

Requesting estimate to connect Lower and Middle Jackson.

COMPLETED TASK ORDERS (Since Oct 2011)

Cost	Location	Damage	Notes
\$ 4,570	Gore north of Youngs	Fixed ditch/culvert	Downstream part of culvert is eroding away. Sinkhole possible
\$ 2,216	Nelson/Mercer Int	Fixed ditch/culvert	Ditch on west side needs to be deepened from 15701 Nelson driveway crest to first culvert along mercer. Ice sheets form at intersection
\$ 2,746	All	Fill/replace snow barrels	